



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

Date: August 3, 2009

Reviewed: LK

Mine Name: Strawberry River	Permit Number: S/013/0008
Operator Name: Rock & Stone LLC	Inspection Date: July 29, 2009
Inspector(s): L Heppler	Time: 6:00 pm
Other Participants: none	Mine Status: ACT

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Bond Renewal Date: 04-15-2010 **Bond Amount:** \$17,000 **Permit fee** is delinquent -\$150

Purpose of Inspection: Routine annual Inspection. This site was inspected as a small mine site on 03/02/2009

Inspection Summary: Every effort should be made to salvage topsoil from the site prior to mining. Five (5) large pieces of equipment on site have rusty buckets, blades and tracks; it is not clear when was the last time the mine was operating. Vegetation has not been established. Product storage area is limited; the majority of the palletted stone has been moved off site. Trash at the site needs to be removed. Area south of the road has not been properly regraded or revegetated. Highwall of the mine site is consistent with natural environment to the east of the mine.

Photos were taken to document site conditions.

Conclusions and Recommendations: Operator has 30 days to comply with all local, state and federal rules; Trash on site to be cleaned up; Permit is considered suspended until Annual permit fee. OGM to continue annual inspections and monitor the site when in the area.

Inspector's Signature

LAH:vs

cc: Cliff Read

O:\M013-Duchesne\S0130008-Strawberry\inspections\Insp-07292009.doc



Note – Rusty tracks and buckets



View of main working area



Southside of the road



Southside of the road